

INTRODUCING PREMIER'S POWERPLUS™ SAFETY STIMULUS PROGRAM



Get \$495 savings on the Premier PowerPlus™ standby alternator for DA40 aircraft.

Even on a sunny day, an electrical system failure is serious. But now you can take the worry out of every flight by having a **Premier PowerPlus** standby alternator installed in your Diamond DA40 by Premier Aircraft Service for only **\$4,995!**

The system is fully automatic. When it senses a voltage drop, the **Premier PowerPlus** standby alternator kicks in with all the electrical power that your G1000 system needs in order to safely make it to the nearest airport.

With Premier's PowerPlus Safety Stimulus Program, there's no reason to make another flight without the added safety, security and convenience of a standby alternator.

Want an even cooler deal?

Get your **Premier PowerPlus** standby alternator at the same time you have a new **DA40 CabinCool™** air conditioning system installed and pay only **\$4,500** for your PowerPlus. That's a total of **\$495 off** the regular price of \$4,995!



For more information on the Premier PowerPlus standby alternator or the DA40 CabinCool air conditioning system contact:

**PREMIER AIRCRAFT SERVICE AT 866.875.4347
OR VISIT WWW.FLYPAS.COM**

Premier
Aircraft Service

WHERE INTEGRITY, EXPERIENCE AND VALUE TAKE FLIGHT

PREMIER POWERPLUS™

MORE POWER TO YOU!

Even on a sunny day, an electrical system failure is serious business. But by simply adding a Premier PowerPlus standby alternator to your Diamond DA40 you can take the worry out of every flight. Here are some frequently asked questions about the Premier PowerPlus standby alternator from Premier Aircraft Service.

Q: How much does the Premier PowerPlus cost?

A: The price for the standalone installation is \$4,995. But, if you have the Premier PowerPlus standby alternator installed in your DA40 at the same time as a DA40 CabinCool™ air conditioning system, the price for PowerPlus drops to \$4,500.

Q: What is Premier PowerPlus?

A: The PowerPlus standby alternator is an FAA approved PMA unit used on other Garmin G1000-equipped aircraft.

Q: How does it work?

A: The system is totally automatic. Once it senses the bus voltage drop below 26 volts, it automatically starts charging the battery. There is an annunciator to alert you that the primary alternator has failed.

Q: How much power does Premier PowerPlus provide?

A: It delivers 20 amps and will operate the entire Garmin G1000 system plus some lighting. There is no limit to how long the system can operate at maximum capacity.

Q: Where is the Premier PowerPlus unit installed on my engine?

A: The unit is installed on the back of the Lycoming engine where the vacuum pump would normally be installed.

Q: Is the Premier PowerPlus available for non-G1000 equipped DA40's?

A: No.

Q: How much does the Premier PowerPlus unit weigh?

A: 7.3 pounds and it moves the C.G. forward slightly.

Q: Can I have my Premier PowerPlus installed at the Diamond factory or by any Diamond Service Center?

A: No. Currently installations may only be performed by Premier Aircraft Service located at Fort Lauderdale Executive Airport (FXE).

Q: How long does the installation take?

A: One day.

Q: Is there any tax benefit available for installing the Premier PowerPlus?

A: This is a fixed asset and qualifies for expensing for qualifying small businesses, or bonus depreciation for others. A qualifying small business may write off the entire purchase this year. If it does not qualify for expensing, it will qualify for 60% depreciation for the 2009 tax year. Consult your tax professional for specific details.

Q: How can I get more information about Premier PowerPlus standby alternator?

A: Call Ray Bysiewicz at 1-866-875-4347 or e-mail Ray at: Ray.Bysiewicz@flypas.com

Premier. Your #1 source for DA40 service and upgrades.

Nobody knows more about servicing and supporting your Diamond DA40 than the experts at Premier Aircraft Service. As a division of Premier Aircraft Sales, Inc., North America's largest Diamond Aircraft dealer, our unsurpassed knowledge and experience will ensure any maintenance, inspections, upgrades or service we perform on your DA40 will be done to your total satisfaction.

Premier
Aircraft Service

CALL RAY BYSIEWICZ AT 866.875.4347

WHERE INTEGRITY, EXPERIENCE AND VALUE TAKE FLIGHT